

Article 33

Stow Town Meeting

Randall Library Flat Roof Replacement & 2nd Floor Roof Top HVAC Unit Replacement

Building Department

EXISTING CONDITIONS

- THE FLAT RUBBER ROOF WAS INSTALLED IN 1991
- OVER THE PAST 10 YEARS WATER LEAKS HAVE BEEN AN ONGOING PROBLEM
- WE HAVE PATCHED THE ROOF MANY TIMES ONLY TO HAVE WATER LEAK IN AT A NEW LOCATION ON THE 2ND FLOOR



EXISTING CONDITIONS (CONT.)

- THE 7.5 TON GAS FIRED ROOF TOP UNIT WAS INSTALLED IN 2000
- AFTER 20 YEARS OF OPERATION THE UNIT IS FAILING AND REPLACEMENT PARTS ARE NOT AVAILABLE
- ◆ THIS UNIT SUPPLIES HEAT AND AIR CONDITIONING TO THE 2ND FLOOR OF THE LIBRARY WHICH INCLUDES THE NEWLY RENOVATED SECTION



PROPOSED FLAT ROOF

- SINCE THE FLAT ROOF AND THE HVAC UNIT ARE INTERGRATED, IT IS PROPESED TO REPLACE BOTH UNDER ONE CONTRACT
- THE FLAT ROOF IS 1,500 SQUARE FEET. REPLACEMENT WOULD BE A 60 MIL EPDM ROOF WITH NEW INSULATION, FLASHING AND DOWNSPOUTS
- ESTIMATED COST: \$40,000



PROPOSED HVAC UNIT

- THE REPLACEMENT HVAC UNIT WOULD BE A 7.5 TON GAS/ELECTRIC HVAC ROOF TOP UNIT
- THE EXISTING DUCT WORK WOULD BE CLEANED AND REUSED
- ESTIMATED COST: \$70,000

