

RANDALL LIBRARY PRELIMINARY DESIGN SERVICES

TOWN OF STOW

designLAB Team:

Ben Youtz, Partner
Mary Ann Upton, Partner
Bob Miklos, Founder
Andrew Brookes, Designer
Erick McGartland, Architect

Consultants:

G2 Collaborative
Fitzmeyer Tocci
RGE Structural Engineers
Nitsch Engineers

Building Committee Members:

Tina McAndrew, Library Director

Lisa Lavina

Jim Salvie

Morgan Hillman

Brian Patuto

Kat Copland

Peter McManus

Town Administrator:

Denise Dembkoski



design LAB architects







Providence Public Library: 1950s Wing Transformation



Claire T. Carney Library, UMass Dartmouth










Providence Public Library: 1912 Building Renovation

designLAB architects



















Somerville West Branch Library, City of Somerville, MA





Somerville West Branch Library, City of Somerville, MA





Somerville West Branch Library, City of Somerville, MA













Somerville West Branch Library, City of Somerville, MA















Programming + Concept Design Schedule Overview





Site + Landscape: (G2 Collaborative)

- Common Road presents an opportunity for more usable social space at the entry to the library and that area could create real connections to the town common space. The library presence would be increased and could benefit from a more gracious entrance as a civic amenity.
- Even without work on Common Road, the library entry should be re-crafted to allow for more seating and social space, formalizing the picnic table/seating area that is there now. All areas of the entry sequence need to be Accessible, including parking.
- The existing roof terrace has limited use as a function space given how sunny (hot) it is. Similarly, the existing amphitheater gets little to no use
- Effort should be made to make the library more noticeable from Crescent St, the views from Crescent St should "invite" visitors to stop and patronize the library.





Architecture + Building Envelope:

- Compromised Entry Sequence
- Several Active Leaks in Roof + Glazing Systems
- Original and 1970's masonry is generally sound. However there are localized areas, some substantial in size, of masonry and stonework that require repair, replacement and/or repointing
- Accesssibility Issues (non-conforming door hardware, restrooms, stair handrails, lack of elevator, etc.)
- Significant Acoustic Challenges (Noise Transfer) within Historic Building and 1970's Addition






Building Systems (MEPFP) Fitzemeyer & Tocci Associates

- The building does not have a fire protection (sprinkler) system.
 Depending on the level of renovation, a fire protection system may or may not be required.
- Building HVAC is currently fed from miscellaneous split systems ranging in age from 2001 to 2017. The newer units (installed in 2017) are in good condition and could potentially be re-used depending on proposed renovation layouts.
- Much of the older equipment is beyond its useful life and will need to replaced as part of future renovation plans
- Main electrical equipment (panelboards) are beyond useful life and main electrical room does not meet National Electrical Code (NEC) clearance requirements
- Existing septic tank and leaching field requires evaluation to determine if it could serve a renovated library or if replacement is required.
- Incomplete fire alarm notification coverage





Structural (Roome & Guarracino Engineers)

- Existing building structure is inadequate to support load of library collection on first floor (Historical Rooms and mezzanine)
- Roof of addition does not meet current code requirements for load capacity
- 1975 foundation and footings are not designed to support additional structural elements.
- Attic level structure not designed to support additional program loads.
- Leaking building envelope (roof, glazing) may be causing additional concealed damage





Library Programs:

- Lack of adult program space
- Disconnected children's spaces
- Underutilized historical spaces
- Lack of quiet spaces
- Inability to have multiple groups meeting at the same time
- Limited staff space







Imagining the Future of Randall Library - We Want to Hear from You!

Fall 2021

VISION

Generally, what do you imagine the future of the Randall Library building looks like?

RESOURCES

What types of resources would you like to see in the Library that do not exist now?

PROGRAM

What types of library programs have you attended in the past? What types of library programs would you like to see offered?

Instructions:

As the The Library Building Committee considers strategies to re-imagine and renovate Randall Library, we want to hear from you! The Building Committee plans to consider this feedback as we develop potential renovation strategies over the next several months. On this board, please:

1. Use post-it notes (as many as you'd like) to share your thoughts on the prompts above





Imagining the Future of Randall Library Building - We Want to Hear from You!

Fall 2021

GATHERING + EVENT

CHILDREN'S ROOM

QUIET READING

GROUP PROJECT ROOMS









OUTDOOR PROGRAM



TEEN AREA

OTHER








Instructions:

As the The Library Building Committee considers strategies to re-imagine and renovate Randall Library, we want to hear from you! The Building Committee plans to consider this feedback as we develop potential renovation strategies over the next several months. On this board, please:


- 1. Use (3) sticky dots to identify which types of spaces you'd like to see in a renovated Randall Library (you can put all (3) sticky dots on one space, or spread them out!
- 2. Use the space to the right of each image to share why these spaces resonate with you on a post-it note.
- 3. Share thoughts on a post-it note on other types of spaces you'd like to see in a renovated Randall Library and why.


















Guiding Principles

- Provide an accessible and inclusive library experience for all
- Create an integrated architectural experience between historic building and renovated 1970's addition and/or new addition
- Provide a variety of program spaces that best meet the needs of both existing and new patrons
- Address all building envelope, building system and maintenance issues
 - Create a more welcoming landscape and entry experience

Proposed Program





Program Statement



Circulation Desk

Office Space


Processing

Break room

Work Room

LIBRARY SUPPORT SPACES








COLLECTION








General Reading

Quiet Reading

READING










CHILDREN'S








MEETING SPACE





Gathering Collection Browsing

YOUNG ADULTS





Providence Public Library: 1950s Wing Transformation



EXTERIOR






Somerville West Branch Library, City of Somerville, MA

























Option A: Reuse

Option B: Add-on

Option C: Re-build

- Least invasive
- A new sprinkler system not required
- Lowest investment

- Realizes fewest program goals
- Buildings do not fundamentally change
- Entry sequence from street is improved though fundamentally does not change
- Renovation results in a 'patchwork' building systems
- Existing septic system reused


 New sprinkler system and new septic system

- Realizes the majority of program goals, though not all
- Hard to 'right-size' spaces
- Complex structural modifications
- Renovation results in a 'patchwork' building systems
- Low floor-to-ceiling height in lower level of 1975 addition
- Higher Investment

- Achieves all program goals and spaces.
- Most opportunity for big impact and 'experiential change'
- Most efficiency in space use
- Most adaptable and flexible for future needs
- Most impactful landscape
- New construction easier to maintain (building systems and envelope)
- New sprinkler system and new septic system
- Higher Ceilings
- Higher Investment

Option B: Add-On Option C: Re-build Option A: Reuse Work Room Break Break LIBRARY SUPPORT SPACES room room COLLECTION Reference Quiet READING Reading YOUNG ADULTS CHILDREN'S Support **TECHNOLOGY** Flexible Meeting Small Small **MEETING SPACE** Meeting Meeting **EXTERIOR**

Program + Building Size Summary





Break-Out Rooms [15 Minutes]

Group 1:

Tina McAndrew (Building Committee Member)
Kat Copland (Building Committee Member)
Ben Youtz (designLAB architects)

Group 2:

Brian Patuto (Building Committee Member)
Morgan Hillman (Building Committee Member)
Mary Ann Upton (designLAB architects)

Group 3:


Lisa Lavina (Building Committee Member)
Peter McManus (Building Committee Member)
Bob Miklos (designLAB architects)
Erick McGartland (designLAB architects)

4 Prompts / Discussion Topics:

- 1) What aspects or features of these early concepts excite you the most?
- **2)** What exterior improvements seem most successful or important?
- **3)** What new program opportunities resonate with you?
- **4)** Was there anything you feel was missing?



Preliminary Cost Estimate



Preliminary Cost Estimate

Base Building Improvements + Building Code Requirements:

Sitework

- Enabling
- Accessibility Improvements
- Site Utilities
- Site Lighting
- New Septic System (B + C)

Architectural

- Accessibility Improvements
- Envelope Repairs + Replacement
- Masonry Restoration
- New Elevator
- Finish Replacement

MEPFP


- New mechanical systems
- New sprinkler system
- New lighting
- New Fire Alarm + Electrical Infrastructure

Soft Costs


- Escalation to Spring 2023
- Moving & Storage Expenses
- Temporary Facilities Expenses
- Fixtures, Furnishings/Shelving & Equipment (A/V, Security, etc.)
- Owner's Project Management (OPM)

Professional Services

- Architectural & Engineering Professional Services
- Construction Utility Services
- Building Commissioning Services
- Hazardous Material Assessment & Disposal Costs
- Permitting, Legal Expenses, Bonding
- Construction Material Testing
- Owner's Contingency
- Geotechnical Services



Next Steps



Next Steps

Option A: Reuse



Option B: Add-on




Option C: Re-build




tmcandrew@minlib.net





First Floor Layout and Program










Second Floor Layout and Program













Historic Study




















Option A - Reuse


Option B- Add-on

Option C- Re-build

Sitework			Sitework		s	Sitework	
Low	\$ 800,000	35	Low	\$1,200,000	L	ow (10%)	\$1,300,000
High	\$ 950,000	33	High	\$1,350,000	H	ligh (30%)	\$1,450,000
					_		
Architectural Improvements			Architectural Improvements	•	Δ	Architectural Improvements	
Low	\$2,000,000	65	Low	\$2,500,000	L	.ow (15%)	\$2,650,000
High	\$2,300,000	00	High	\$2,800,000	H	High (30%)	\$3,000,000
MEPFP Improvements			MEPFP Improvements			MEPFP Improvements	
Low	\$1,250,000	100	Low	\$1,600,000		ow (15%)	\$1,450,000
High	\$1,400,000	100	High	\$2,050,000		ligh (30%)	\$1,650,000
riigii	\$ 1,400,000		riigii	\$ 2,000,000		ligit (50 %)	V 1,000,000
Construction Cost Total			Construction Cost Total		C	Construction Cost Total	
Low Range	\$4,050,000		Low Range	\$5,300,000	L	.ow Range	\$5,400,000
High Range	\$4,650,000		Low Range	\$6,200,000	H	ligh Range	\$6,100,000
Escalation (7.5% - spring 2023)			Escalation (7.5% - spring 2023)	1	E	scalation (7.5% - spring 2023)	
Low Range	\$4,350,000		Low Range	\$5,700,000	L	ow Range	\$5,800,000
High Range	\$5,000,000		High Range	\$6,650,000	Н	ligh Range	\$6,550,000
Soft Costs (35%)			Soft Costs (35%)		S	Soft Costs (35%)	
Low	\$1,500,000		Low	\$2,000,000		.ow	\$2,000,000
High	\$1,750,000		High	\$2,300,000	H	High	\$2,300,000
T-4-1044			Total Contract		-	Total Contract	
Total Contract	¢ = 0=0 000		× 1	\$7,700,000			\$7,800,000
Low	\$5,850,000		Low			.OW	\$8,850,000
High	\$6,750,000		High	\$8,950,000	-	ligh	\$ 6,630,000



Large Flexible Small Meeting Meeting Meeting







Combine best meeting spaces w/ previous slide - 1 slide only... Too large of a space? Mass art or wbl

Program Summary

Option A: Reuse



Option B: Add-on



Option C: Re-build



Option A: Reuse

- Historic building and 1975 addition do not fundamentally change: same footprint and square footage
- Least invasive, but realizes fewest programmatic goals and limited opportunity for big impact and 'experiential change'
- Entry sequence from street is improved though fundamentally does not change

Option B: Add-on

- Realizes the majority of program goals, though not all
- Due to existing footprint and plan configuration there is limited opportunity to 'right-size' spaces for their programmatic use
- Significant (and complex) structural modifications to 1975 addition to create additional square footage on main level and new roof configuration

Option C: Re-build

- Achieves all program goals and spaces. Most opportunity for big impact and 'experiential change'
- New addition construction facilitates the most **efficiency** in space use
- Most adaptable and flexible for future needs
- Opportunity for most transformative landscape

- Renovation results in a 'patchwork' approach to building systems
- A new fire protection system (sprinkler) is not necessitated by code.
- Existing septic system is reused

- Similar to A, renovation results in a 'patchwork' approach to building systems
 - New sprinkler system and new septic system to support increase in size and use
- Low floor-to-ceiling height in lower level of 1975 addition

- New construction provides best ease of maintainability in both building systems and envelope
 - New sprinkler system and new septic system to support increase in size and use
- Higher Ceilings on lower level