

RANDALL LIBRARY PRELIMINARY DESIGN SUMMARY

TOWN MEETING - 5/14/2022 STOW, MA

Building Committee Members:

Tina McAndrew, Library Director

Lisa Lavina

Jim Salvie

Morgan Hillman

Brian Patuto

Kat Copeland

Peter McManus

Town Administrator:

Denise Dembkoski

designLAB Team:

Ben Youtz, Partner
Mary Ann Upton, Partner
Bob Miklos, Founder
Andrew Brookes, Architect
Erick McGartland, Architect

Consultants:

G2 Collaborative
Fitzmeyer Tocci
RGE Structural Engineers
Nitsch Engineers





INTRODUCTION

LIBRARY | HISTORIC BUILDING EXPERIENCE



BOSTON ATHENAEUM



HYDE PARK LIBRARY



PROVIDENCE PUBLIC LIBRARY



WHITIN OBSERVATORY



MASSART ART MUSEUM



WEST BRANCH LIBRARY



NEEDHAM PUBLIC LIBRARY



OIL CITY NATIONAL BANK



CONCORD MUSEUM



CURLEY COMMUNITY CENTER

INTRODUCTION CRITICAL STEWARDSHIP






PROGRAMMING + CONCEPT DESIGN SCHEDULE OVERVIEW

Summer + Fall 2021


Programming + Concept Design



COMMUNITY PROCESS

Summer + Fall 2021


Programming + Concept Design




Guiding Principles

- Provide an accessible and inclusive library experience for all
- Create an integrated architectural experience between historic building and renovated 1970's addition and/or new addition
- Provide a variety of program spaces that best meet the needs of both existing and new patrons
 - Address all building envelope, building system and maintenance issues
 - Create a more welcoming landscape and entry experience

DESIGN PROCESS OVERVIEW



DESIGN PROCESS OVERVIEW




COMMUNITY PROCESS







DESIGN PROCESS OVERVIEW



BUILDING CODE, STRUCTURAL + ENVELOPE





BUILDING CODE, STRUCTURAL + ENVELOPE





Building Department installed a semi-permanent tarp on the inside to funnel the leaks into a bucket





2021 leak on slanting windows in Children's Area on Crescent Street side







Recurring roof leak damage on the second floor of the 1970's addition

BUILDING SYSTEMS





LANDSCAPE + ARRIVAL






LIBRARY PROGRAMMING





PROPOSED PROGRAM





Program Statement



Option A: Reuse




Option B: Add-On



Option C: Re-build









Option A: Reuse

Option B: Add-on

Option C: Re-build


- Least invasive
- A new sprinkler system not required
- Lowest investment
- Realizes fewest program goals
- Buildings do not fundamentally change
- Entry sequence from street is improved though fundamentally does not change
- Renovation results in a 'patchwork' building systems
- Existing septic system reused

 New sprinkler system and new septic system

- Realizes the majority of program goals, though not all
- Hard to 'right-size' spaces
- Complex structural modifications
- Renovation results in a 'patchwork' building systems
- Low floor-to-ceiling height in lower level of 1975 addition
- Higher Investment than Option A: Reuse


- Achieves all program goals and spaces.
- Most opportunity for big impact and 'experiential change'
- Most efficiency in space use
- Most adaptable and flexible for future needs
- Most impactful landscape
- New construction easier to maintain (building systems and envelope)
- New sprinkler system and new septic system
- Higher Ceilings

 Higher Investment than Option A: Reuse




OPTION C- REBUILD ADDITION Circulation **Break** Work Processin<u>a</u> Space Children's Children's Program Collections General Level 2 Collection Browsing TERRACE Collection Program Support PLANTING Modern Tech **Flexible** Library Flexible Program Small PLAZA Library Gather **Program** Space LAWN TERRACE 22 The state of the s Level 1

HISTORIC CONTEXT







HISTORIC CONTEXT

HISTORIC BUILDINGS IN STOW



GATES HOUSE



STOW TOWN HALL



PARISH CHURCH



GLEASONDALE MILL

NATIONAL REGISTER OF HISTORIC PLACES IN STOW



WALCOTT-WHITNEY HOUSE



BROWN STOW HOUSE



RANDALL HALE HOMESTEAD



TENNEY HOMESTEAD



HAPGOOD WHITNEY HOUSE

HISTORIC CONTEXT

RANDALL COMPOSITION

















ENTRY HALL VIGNETTE



CHILDREN'S SPACE VIGNETTE



EXISTING ENTRY



EXTERIOR VIGNETTE SOUTH VIEW



EXISTING NORTH ELEVATION



EXTERIOR VIGNETTE NORTH VIEW




EXTERIOR VIGNETTE EAST VIEW




EXTERIOR VIGNETTE EAST VIEW






DESIGN PROCESS OVERVIEW



DESIGN PROCESS OVERVIEW





SUSTAINABILITY


















Dartmouth Hall, Dartmouth College



Flow consider one directional flow



Pick Up infrastructure for pick up service model



FIEX FLEXIBLE FURNISHINGS (SMALLER MODULES) FOR EASE OF REARRANGEMENT & SPACING OUT




Fresh Air outdoor program spaces & open up to outdoors



Hybrid Infrastructure for online & Hybrid Programs

Program + Building Size Summary



Preliminary Cost Estimate

Base Building Improvements + Building Code Requirements:

Sitework

- Enabling
- Accessibility Improvements
- Site Utilities
- Site Lighting
- New Septic System (B + C)

Architectural

- Accessibility Improvements
- Envelope Repairs + Replacement
- Masonry Restoration
- New Elevator
- Finish Replacement

MEPFP

- New mechanical systems
- New sprinkler system
- New lighting
- New Fire Alarm + Electrical Infrastructure

Soft Costs

- Escalation to Spring 2023
- Moving & Storage Expenses
- Temporary Facilities Expenses
- Fixtures, Furnishings/Shelving & Equipment (A/V, Security, etc.)
- Owner's Project Management (OPM)

Professional Services

- Architectural & Engineering Professional Services
- Construction Utility Services
- Building Commissioning Services
- Hazardous Material Assessment & Disposal Costs
- Permitting, Legal Expenses, Bonding
- Construction Material Testing
- Owner's Contingency
- Geotechnical Services

